

TASCAM DP-24 Release Notes

< Maintenance items >

■ V1.02(Build#0051) fixes

- When the recording starts from other than 00:00, it's stopped recording if the recording mode is set to "44.1kHz/24bit". This has been fixed.
- The slave side occasionally stops caused by the timing of MTC output messed up. This has been fixed.
- Can't read some WAV files. This has been fixed.
- Performance has been more stabilized.